


# Top view



1>+ 3.3V  
2>0V ON ALL BLOCKS

	I/OBLK1	I/OBLK2	I/OBLK3
3>	P0	P8	P16
4>	P1	P9	P17
5>	P2	P10	P18
6>	P3	P11	P19
7>	P4	P12	P20
8>	P5	P13	P21
9>	P6	P14	P22
10>	P7	P15	P23